## ABSTRACT OF THE DISCLOSURE

5

A method for recycling glass includes the steps of: (a) mixing glass shards with carbon powders so as to permit adhesion of the carbon powders to the surface of each glass shard, (b) heating the glass shards so as to melt the surface of each glass shards, (c) cooling the heated glass shards, and (d) removing the carbon powders from the glass shards.